




Headliner and foam backing has been removed



Port side cabinetry removed in order to insulate hull, deck and coach top

Port side aft lower shroud backing plate



Starboard side aft lower shroud backing plate





Headliner and foam backing has been removed

Headliner and foam backing has been removed under starboard side deck



Traveller backing plate



Firing strips around traveller space and cabin side



Insulation has been glued between firing strips



Insulation has been glued between firing strips



Insulation has been glued between firing strips



FRP headliner screwed into place



Teak bats have been added to complete the project




Teak bats have been added to complete the project looking aft



Other views







A variety of trim joints



V-berth



Cuts made so that board would bend to curve of cabin top

